

Facility Name: Utica Resource Operating, LLC – Stiers Well Pad
Facility Location: 39.95118, -81.4348, Wills Township, Ohio
Date of Inspection: April 18, 2019

APPENDIX A: DIGITAL IMAGE/VIDEO LOG

1. Inspector Name: Victoria Nelson	2. Dates of Inspection: April 18, 2019
3. Company/Facility Name: Utica Resource Operating, LLC – Stiers Well Pad	4. Street Address, City, State: 39.95118, -81.4348, Wills Township, Ohio
5. Number of Images and Videos: 15	6. Archival Record Location: C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2379.mp4	4/18/2019	Emissions from combustor stack - combustor was not operating
2	MOV_2380.mp4	4/18/2019	Emissions from Tank 75246 thief hatch
3	MOV_2381.mp4	4/18/2019	Emissions from Tank 75250 thief hatch
4	MOV_2382.mp4	4/18/2019	Emissions from top of tank battery during dump
5	MOV_2383.mp4	4/18/2019	Emissions from Tank 75249 thief hatch
6	MOV_2384.mp4	4/18/2019	Emissions from Tank 75247 thief hatch
7	MOV_2385.mp4	4/18/2019	Emissions from Tank 75253 thief hatch
8	MOV_2386.mp4	4/18/2019	Emissions from Tank 75248 thief hatch
9	MOV_2387.mp4	4/18/2019	Emissions from Tank 75252 thief hatch
10	MOV_2388.mp4	4/18/2019	Emissions from Tank 76061 thief hatch
11	MOV_2389.mp4	4/18/2019	Emissions from Tank 75600 thief hatch
12	MOV_2390.mp4	4/18/2019	Emissions from Tank 76060 thief hatch

Facility Name: Utica Resource Operating, LLC – Stiers Well Pad
Facility Location: 39.95118, -81.4348, Wills Township, Ohio
Date of Inspection: April 18, 2019

Image Number	File Name	Date and Time (Eastern Time)	Latitude and Longitude	Description of Image
1	P4180027.JPG	4/18/2019 12:18:56 PM	39.977778, -81.419167	Paraffin build-up, staining, and condensate droplets from Tank 76060 thief hatch and tank roof equipment
2	P4180028.JPG	4/18/2019 12:19:01 PM	39.977778, -81.419167	Paraffin build-up and staining at Tank 76060 threaded connection
3	P4180029.JPG	4/18/2019 12:19:08 PM	39.977778, -81.419167	Paraffin build-up, staining, and condensate droplets from Tank 76060 thief hatch